

6.2.2 Linear Buckling analysis

The linear buckling factor is 1695.5 by pressure as Fig. 6.6. It's more than 2.5. And the buckling factor is occurred at shell.




Fig. 6.6 Linear buckling